Annexure D

BUILDING SAFETY CERTIFICATE

	No. 001/24 Dated: 14/3/24							
	It is certified that the existing building							
	building or premises) at							
	Detail of Block(s) in	Block	Block	Block	Block	Block	Block	
	school	(1)	(2)	(3)	(4)	(5)	(6)	
	No. of Floor(s) in the Block	Sergle	Sengle	Single	Single	Sugle	Serok	
234	The building is owned/occupied by Green Field (name							
	of the Institution) have of			safety require				
+	Building code Rules, and verified by the officers concerned of Assert engineer (Name of Department/ Govt.) on Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 1989 for a period of secretary or his recordance							
	with rule and subject to compliance of the specific conditions as appended. 1. The work has been completed to my best catchineation. 2. The work manghap and all the materials have been used structed in a accordance with general and detail satisfication. 3. The bendering is streed tially sound and sate and by school. 4. Hence of is fit for whe haw in with Greenfield school is running. Issued on 1413 24 and at the paythers by Accord Engineer 150. A KIP							
	* Strike out whichever is not applicable. In case of block is more than six use separate sheet for							
	detail.					pho	5.	
	Signature with Seal:							
					Name :	The Lines	and all	
		Name & Address of Department/ Office:						
	66 Page			and the second	- Soparaner), [KJR KJR	

To,

The Principal

Greenfield School

At/Po-Palaspanga

Dist-Keonjhar, Odisha

School Udise Code-21061015252

CBSE Affiliation No-1530024

School No-15370

Sub:- School building safety inspection report in favour of Greenfield School, Palaspanga, Keonjhar Respected Sir/Madam.

With reference to the subject cited above this is to intimate that as per Plan school is functioning in 5 no. of buildings. All the buildings are of single storied. Built up area of block -1 is 246.4 sqm, block -2-553 sqm,block-3-301 sqm block-4-257.8 sqm and block five office building is of 233.5 sqm. All the buildings are separated from each other and adequate open space is available. The height of each building is less than 9mtrs. It is R.C.C framed structure Building. The rooms of the buildings are safety condition for smooth running of the classes.

I, certify that I have inspected the Greenfield school, Palaspanga building on 24/02/2021 referred to above and examined the various parts including the foundations with special reference to the class rooms. I am of the opinion that the buildings are in accordance with the plans. These buildings are structurally sound and stability will not be endangered by their use as school.

Chaturbhuja Nayak

Sadar Block, Keonjhar

Keonjhar

